


Plated parts and stainless steel bolts




- ① L6 plated tappet cover ¥40,000
- ② L-shaped plated thermo cover (2 bolts) ¥5,000 (Stainless steel bolts and gasket included)
- ③ L-shaped plated thermo cover (3 bolts) ¥4,500 (Stainless steel bolts and gasket included)
- ④ L6 Plated Water Pump Pulley ¥10,000 (Stainless bolts included)
- ⑤ L6 plated head front cover ¥3,300 (Stainless steel bolts and gasket included)
- ⑥ L-shaped plated head triangular cover ¥4,000 (Stainless steel bolts and gasket included)
- ⑦ L 6 Plated tappet cover bolt ¥3,600
- ⑧ L4 plated tappet cover bolt ¥2,700
- ⑨ L-type front cover stainless steel bolt set ¥3,000
- ⑩ Nissan-type plated hub cap set ¥4,500 (2 pieces set)
- ⑪ L4 Plated Mechanical Pump Cover ¥5,000 (Stainless steel bolts and gasket included)
- ⑫ L-shaped plated oil filter cover ¥5,000

*Only the tappet cover is a standard replacement price.
*In addition to the yL-shaped front cover stainless bolt set, you can add 4 oil pump bolts and 2 thermo housing bolts.
Total ¥4,000/1set




Plating/Sheet/Mirror

S30 Boots Set (Leather)



Shift lever & side lever boots set 1set ¥5,000

S30 Boots Set (CarbonPattern)



Shift lever & side lever boots set Discontinued

Vitaloni California



Universal door mirror (left and right set) 1 set ¥24,000 (Mirror height x width x length x projection) 92 x 144 x 101 x 148

Classic Type



Universal fender mirror (left and right set) 1 set ¥20,000 (Mirror diameter x total length x height) φ103 x 125 x 110

Classic Type



Universal fender mirror (left and right set) 1 set ¥24,000 (Mirror diameter x total length x height) φ103 x 125 x 110

GT bucket seat



Production stoppage
KAMEARI bucket seats for historic cars made of high-quality leather. Universal aluminum stays are included, so they can be installed on the genuine seat rails with a little modification.

S30 genuine seat repair kit



• Early model (up to April 1971) with horizontal stitching. Product number: SE4604, left and right set, ¥75,000
• Early model (S46/May-48) Horizontal stitching Product number: SE4812 Left and right set ¥75,000
• Late model (from January 1974) with vertical stitching. Product number: SE4901, left and right set, ¥75,000
This is a seat reupholstery repair kit made for users who are particular about genuine seats that are no longer manufactured.

S30 European Grill

Fits: 1969-1978 High quality aluminum construction with powder coated finish Billet aluminum (extruded)

¥45,000 (Updated 2025.09.03)



S30/GC10 emblem

- ① Datsun emblem ¥5,000
- ② S30 Datsun Front Fender ¥5,000
- ③ S30 Datsun Rear Gate ¥3,500
- ④ GC10 GT-kai Front Grille Discontinued
- ⑤ GC10 GT-modified rear Production stoppage

Steering boss



Part number	Compatible models
S-021	S30, S130, C130, GC10-R30, 510, 230-430 (Note) GC110 is not compatible
S-022	B110-210
S-01	TE series (S49.3-), TA series (S52.8-), KP61
S-03	TE27series(-S49.3), TA22 series (-S52.8), KP45-51
Price : ¥5,000	*Compatible with Momo, Nardi, Personal, etc.

Wheel cap emblem

① DATSUN-01



② DATSUN-02



③ Z-01



Outer diameter x thickness: 48φ x 1.0
Material: Water-resistant vinyl coated finish
*Stick-on type that can be attached by peeling off the backing paper.

- ① DATSUN-01 ¥2,500 (2-disc set)
- ② DATSUN-02 ¥2,500 (2-disc set)
- ③ Z-01 ¥2,500 (2-disc set)